NFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

proc	Essing Copy	S-E-C-R-E-T		25X1
COUNTRY	Hungary / Poland / C ₂ Rumania / USSR / Situation on Aircraft Satellite Countries.	; Spare Parts in	REPORT DATE DISTR. NO. PAGES	29 March 1957 25X1
	Soviet Deliveries		REQUIREMENT NO.	RĐ: .
DATE OF INFO.			REFERENCES	25X1
PLACE & DATE ACQ			•	25X1
	in Hungary, Poland, C the situation in Hung the USSR.	zechoslovakia, and	Rumania. The	n aircraft spare parts report deals mainly with ield on supplies from
			•	(363
				25X1

N

25X1

<u> </u>	00 2							Ļ
STATE	X ARMY	XNAVY	XAIR	X FBI	AEC	′	l	

25X1

SFEDER

SECRET

25X1

HUNGARY/SOVIET BLOC

Air/Sconomic/Folitical

Spare Parts Situation in the Hungarian Air Force from

1951 - 1956

Planning within the Hungarian Air Force

The supply of aircraft spare parts to the Hungarian Air Force from 1951 to 1956 was so critical that at NO time during that period could it be said that the Hungarian Air Force was in a state of complete preparedness.

- 2. The main single reason for the critical spare parts position was the inability of the Hungarian Air Force Engineering Service to attempt any satisfactory forward planning of spare parts requirements and production since, owing to factors completely outside their control, it was impossible to forecast the numbers or, indeed, the types of aircraft which would be in service at a given time.
 - 3. The actual supply of aircraft for the Hungarian ir Force depended ded entirely upon the U.S.S.R. and its decisions as to which aircraft should be made available. Thus in 1951 MiG 15s were supplied followed in 1952 by Tu 2s and, in late 1952, by MiG 15 (bis). No new types of aircraft were provided until 1956 when MiG 17s, which were scheduled for delivery in 1957, were surdenly received by the Hungarian Air Force and, at the same time, it was announced that MiG 19s due for delivery in 1957/1958, would be delivered in December, 1956.
 - 4. The condition of the aircraft received from the U.S.S.R. was nover satisfactory. Such aircraft had invariably already completed at least 200 flying hours and were due to be grounded for a major overhaul (in cortain cases this was already the second major overhaul in the aircraft's life) and, in a great number of cases, that overhaul completely exhausted the very modest quote of spars pages

25X1

23/

SECRET

' 25X1

- 0 -

originally delivered with the airgraft.

- 5. It was, intheory, possible for the Hungarian Air Force to order spare parts from the Soviet Union and also from Folend and Czechoslovakia but, even when they placed such orders (the delay in delivery was always some 6 12 months), matters solded went smoothly. There was, in such cases, an initial difficulty in obtaining the necessary Hungarian Ministerial approval for the financial outlay but, even when the indents had gone through, there were many cases of the necessary spares being non-available, a fact which did not, however, prevent the Russians on every occasion sending spare parts of some kind to the value of the original order, for which order "Valuta forints" had already been received by the Russians.
- 6. The procurement of suitable spare parts from Poland and Czechoslovakia and even the U.S.S.R., was further complicated by the fact
 that, even when the correct spare parts were supplied, there were very
 many occasions on which they were not exact replacements for the
 defective component. This was undoubtedly due to the existence of
 many series of the same aircraft type and variations within each
 series, depending on the factory of manufacture of the aircraft.
 Thus, on close examination it was found that there were 56 variations
 within the 150 Tu 2s in service with the Hungarian Air Force.
- 7. It appears almost cortain that this strikingly large number of varied aircraft can be attributed to be very poor quality of manufacturing plans supplied to Soviet aircraft factories. It is cortain that specifications were inexact or insufficient and it appears likely that variations in design have resulted from local chief engineers being themselves forced to fill in blanks in plans supplies.
- 8. Confronted on the one hand by these difficulties in obtains spore parts from the WARRAN Pact countries and, on the other

th

SECRET

25X1

SECRET

· 3 -

25**X**1

the operational demand to keep the maximum number of serviceable condition, the Hungarian Air Force Engineering Service decided that the only solution lay in the production in Hungary of the necessary spare parts. and the problem was handed over to their Industrial Section.

- 9. From the delivery of the MiG 15s in 1951 until 1953, there were constant discussions between the Hungarian Air Force, the army Council and the Ministry of Defence in an attempt to obtain permission to begin manufacture of spare parts in Hungary but the attitude of Ministers (including RAKOSI, when the matter was referred to him personally in 1952) was entirely non-committed and it was not until late 1953, when the situation regarding the MiG 15s had become quite desperate, that reductant approval was eventually forthcoming.
- 10. From the middle of 1952 enwards, officers of the Hungerian Lir Force Engineering Service Industrial Section had secretly begun to plan for the eventual production of spare parts. They found themselves handicapped from the outset by their lock of satisfactory aircraft manuals for the MiG 15s and the complete non-availability of even the simplest manufacturing specifications for MiG 15 components

it was decided, therefore, that it would be necessary to have special drawings made for each component to be manufactured. In late 1952 officers of the Hungarian Air Force Engineering Service Industrial Section secretly removed a number of defective components from MiG 15s grounded in aircraft repair establishments and handed these ever to AGTI (Italanes Geptervez8 Inoda) and BUDLORS. AGTI produced the necessary manufacturing specifications and then passed these to factories with instructions to propare for their production giving at the same time, details of the number of components initially quired. Thus in 1953, when Ministerial approved was eventually given.

/plons 60000000

25X1

SECRET

25X1

- 4 -

plans for production were almost complete.

- 11. In June, 1956, whon MiG 17s first arrived for the Hungarian Air Force, steps were <u>immediately</u> taken by engineer officers to acquire components which they know to require regular replacement and to have manufacturing specifications propared by AGTI and forwarded to the factories. It was heped that by taking such speedy action, it might prove possible to keep the MiG 17s in a better state of repair than had been possible in the case of the MiG 15s.
- 12. The announcement in July, 1956, of the impending arrival of MiG 19s convinced Hungarian Air Force engineering officers that they must, however, find a more radical solution to their spare parts problems and Soviet permission was sought and eventually obtained for a group of Hungarian Air Force engineering officers and civilian aircraft engineers to visit the U.S.S.R. in December, 1956, to study the Soviet aircraft industry with special emphasis on the manufacture and repair of MiG 19s and also the aircraft spare parts problem. Ministerial approval had been given to the Hungarian delegation to purchase what spare parts they could obtain for MiG 17s and MiG 19s as well as II 28s, and the sum of three million roubles had been made available for this purpose.

Hungarian Production of Aircraft Spare Parts

- 13. The supply of aircraft spare parts for the Hungarian Air Force was by no means solved when a decision was forced out of the Ministry to allow production in Hungary because the Hungarian aircraft and allied industries were not in a position to cope with the Hungarian Air Force requirements.
- 14. Directorate I of the Hungarian Ministry of Smolting, which

/VID.B

25X1

SECRET

25X1

SFERET

25X1

- 5 -

was responsible in theory for the production of aircraft and aircraft spare parts, was in no degree enthusiastic about production of complicated and costly series produced components and this was reflected in the tooling in factories producing spare parts. Such factories were, in general, tooled for 60% capacity on mass produced spare parts (e.g. belts, rivets, plating, tubes, etc.) and, at most, 40% capacity on series produced spare parts (e.g. compressors, hydraulic system components, special bearings, etc.) and no serious attempt was being made by the responsible Ministry to arrange for essential re-tooling required by the introduction of jet aircraft and the resultant demand for more and more series produced components.

- 15. In addition, the Hungarian directaft industry was constantly short of the special raw materials required for many jet directaft components since there was a great reductance on the part of the steel works to produce small quantities of special steels and alloys required and all these factors resulted in a constant shortage of spare parts and the consequent grounding of aircraft for long periods.
- 16. In 1956 the main shortages were:
 - a) Carbon stool and duralium high pressure flexible fuel leads.
 - b) Duralium wiro.
 - c) King pins and special short rivots.
 - d) Fuel and hydraulic system pumps.
 - o) Flap components.
 - f) Cable locking components.

Situation in Poland and Czochoslovakia

17. The circulate spare parts situation in Poland and Czochoslovakia was also unsatisfactory but in neighbor of these countries was it as

CFERFT

25X1

/bad...og

25X1

SFCRET

25X1

-6-

bad as in Hungary as both word more highly industrialized and had fairly well developed aircraft industries.

- 18. It was clear in technical discussions between Hungarian, and Polish, and Hungarian and Czoch Air Force officers that in Poland and Czochoslovakia those at Ministerial and Army Council level appeared to be more interested in the planning of their own countries industries and much more adopt at dealing with the Seviet "advisors" attached to their staff. This general aptitude for evolving a solution to problems was reflected throughout the aircraft industry of these two countries but with differing results. The Czochs, when faced with poor Seviet specifications or their own inability to produce raw materials, would alter and, if necessary, improve or compromise to suit themselves (e.g. Il.28/PRHA), whilst the Poles simply copied specifications faithfully and, if matters went wrong, shelved the project, demanded and obtained the necessary detailed specifications, actual spare parts or, even replacement aircraft elsewhere.
- 19. There was a very close technical co-operation between the Polish and Gzech Air Forces and, on many occasions, either Air Force would telephone the other if short of an important spare part and, if it was available, have it collected by courier aircraft. On several occasions, however, even this co-operation was of little avail owing to the lack of standardization of components already described.

<u>kumania</u>

20. From the limited limison which existed between the engineer

/ing.,...

25X1

SECRET

25X1

- 7 -

ongineering services of the Rumanian Air Force and the Hungarian Air Force, it is known that the spare parts situation in Rumania was even more critical than in Hungary. Rumania, having virtually no aircraft industry, was forced to rely on supplies from the Soviet Union and, as these were quite unreliable, the Rumanian Air Force was constantly fared with the problem of a large proportion of its aircraft being grounded for repairs. The attitude of the Rumanian efficors appeared to be a philosophical acceptance of the fact: "if the Russians don't send us spares, we don't fly".

Attitude of Soviet Advisors

- 21. The Soviet advisors attached to the Hungarian Air Force appeared quite unconcerned by the increasingly chaotic spare parts position in the Hungarian Air Force. Their main interest was to ensure that some sort of temperary solution was found to each fresh crisis with a view to keeping as many aircraft as possible serviceable for at least a few more hours! flying.
- 22. Engineer officers of the Hungarian Air Force tried on many occasions to discuss the wider implications of the situation with these advisors and tried to gain ideas from the advisors' experience of Seviet methods. It may be that the Russian advisors were particularly careful not to disclose any information but the impression obtained from these discussions was always that the advisors' experience was limited to Air Armies and that they had no knowledge or interest in wider problems of logistics, nor were they, indeed, expected to be able to advise the Hungarians on such problems.

25X1